

Winterization Checklist

Sample Customer

4700 N 27th St., Tawas City, MI 48763

Aug/25/2023, 10:19pm CDT

12/12 Tasks Completed



Mobile RV Tech Services

PO Box 609, East Tawas, MI 48730

Steve Puvalowski

help@mobilervtechservices.com

9898207373

Job Information

✓ Customer & RV

Customer:

Sample Customer

RV:

2020 Open Range 371MBH

Generator:

Onan 5,500 -Gas



Winterization - Basic Package

✓ Holding Tanks Drained

Fresh Water Tank

Yes

No

N/A

Grey Water Tank(s)

Yes

No

N/A

Black Water Tank(s)

Yes

No

N/A

Notes:

✓ **Water Heater**

Power Turned Off

Switch On Water Heater Circuit Breaker N/A Gas Only

Drained

Yes No N/A

Put Into Bypass Mode

Yes No N/A

Remove Plug/Anode Rod & Inspect

Yes No N/A

Notes:

✓ **Fresh Water Lines**

Inline Water Filter Removed

Yes No N/A

Open Faucets & Low Point Drains

Yes No N/A

Blow Out Supply Water Lines

Yes No N/A

Blow Out Fresh Tank to Pump Line

Yes No N/A

Notes:

RV will need a set of 3 new water filters in the spring.



✓ RV Antifreeze

Fresh Water Lines

Ice Maker

Yes

No

N/A

Kitchen Sink

Yes

No

N/A

Bathroom Sink(s)

Yes

No

N/A

Inside Shower(s)

Yes

No

N/A

Toilet(s)

Yes

No

N/A

Washing Machine Connections

Yes

No

N/A

Outdoor Shower/Spray Port(s)

Yes

No

N/A

Outdoor Kitchen Sink

Yes

No

N/A

City Water Inlet Check Valve

Yes

No

N/A

Black Tank Flush Line

Yes

No

N/A

Notes:

Pump was disconnected to drain the system and reconnected to put in antifreeze.



✓ RV Antifreeze

Drain Traps

Sinks

Yes

No

N/A

Shower

Yes

No

N/A

Toilet(s)

Yes

No

N/A

Washing Machine Drain

Yes

No

N/A

Notes:

Winterization - Plus Package (All the basic items with requested add-ons)

✓ Service & Flush Tank(s)

Flushed (If has built in flushing system)

Yes

No

N/A

Cables Treated w/WD-40 Dry Lube

Yes

No

N/A

Valve Closed After Draining

- Yes
- No
- N/A

Notes:



✓ RV Generator

Stabil Added to Fuel Source


- Yes
- No
- N/A

Ran & Exercised for 15 Minutes

- Yes
- No
- N/A

Notes:

Generator oil is due to be changed in the spring.



✓ Batteries

Disconnected

- Yes
- No
- N/A

Removed for Customer Storage

Yes No N/A

Notes:

✔ Slideout Maintenance

Slideout Sealant Condition

Pass Fail N/A

Seal Inspection Condition

Pass Fail N/A

Treat Slideout Seals

Yes No N/A

Lubricate Gear Tracks

Yes No N/A

Slideout Alignment

Acceptable Position Adjusted to Allow for Proper Sealing N/A

Notes:

The tops of the slideout seals are starting to rip where the cables go through them.



✔ Roof & Sidewall Sealant Inspection

Roof Material Condition

Pass Fail N/A

Roof Sealant Condition

- Pass
- Fail
- Needs Immediate Attention
- Needs Future Repair Work
- N/A

Sidewall Sealant Condition

- Pass
- Fail
- Needs Immediate Attention
- Needs Future Work
- N/A

Notes:

There are cracks in the roof sealant by the bathroom vent fan. It is recommended to repair these before winter.



Job Completion Notes

Wrap Up

Keys

- Gave back to customer
- Put back in hiding spot
- Customer opened RV
- Still in our possession

Parts needed for spring de-winterization:

- Water filters
- Change generator oil

Repairs Needed:

- Roof sealant by bathroom vent
- Slideout seal repair